




CRITICAL TO QUALITY CLASSIFICATION TABLE				
P=PERFORMANCE, F=FIT, A=ASSEMBLY X=IDENTIFIES APPLICABLE CLASSIFICATION(S) ◇=ENGINEERING AND/OR MANUFACTURING REQUIREMENT Ⓢ=REGULATORY REQUIREMENT-CONFORMANCE IS MANDATORY				
COMMENTS	DRAWING ZONE	◇ P	◇ F	◇ A
ROHS	GI-HI			X



3D VIEW


Catalog No	Model/Dir No	Material No
140MT-C-ASA11	10005886127	PN-513869
140MT-C-ASA20		PN-513871
140MT-C-ASA02		PN-514006

MUST COMPLY WITH ROCKWELL
AUTOMATION ENVIRONMENTAL
SPECIFICATION 970-20-01

-Dimensions are shown in mm [inches]
-Dimensions are not intended to be used
for manufacturing purposes

ALL UNDIMENSIONED
GEOMETRIES ARE
CONTROLLED BY THE
CAD MODEL. IN CASE
OF DIMENSION
DISCREPANCY, CAD
MODEL OVERRIDES.

FIRST ANGLE PROJECTION



**Rockwell
Automation**

CONFIDENTIAL AND PROPRIETARY INFORMATION.
THIS DOCUMENT CONTAINS CONFIDENTIAL AND PROPRIETARY
INFORMATION OF ROCKWELL AUTOMATION, INC. AND MAY
NOT BE USED, COPIED OR DISCLOSED TO OTHERS, EXCEPT
WITH THE AUTHORIZED WRITTEN PERMISSION OF ROCKWELL
AUTOMATION, INC.

140MT-C-ASA

DATE: 2021-08-23

SHEET 1 OF 1

SIZE

DIR

VER

A3

10006012929

00

CREATED BY: RPAMPAT

CHANGED BY: PKLANDE